

Vail Home and Condo Inspections

09:25AM August 09, 2009

Photo Attachments



PIC 1: Open ground wire and defective GFI outlet in the master bathroom.



PIC 2: Door from garage to the interior has some damage to the door jam.

Vail Home and Condo Inspections

09:25AM August 09, 2009

Photo Attachments



PIC 3: Surface damage to interior door (2nd level west bedroom).



PIC 4: Casement window in the East basement level bedroom does not shut flush to the jam.

Vail Home and Condo Inspections

09:25AM August 09, 2009

Photo Attachments



PIC 5: West facing awning window in the basement living room failed to open at the time of the inspection.



PIC 6: South facing basement casement window appears to have broken seals.

Vail Home and Condo Inspections

09:25AM August 09, 2009

Photo Attachments



PIC 7: Grout repairs for East 2nd level bathroom room.